



Hotel Roof Waterproofing



PROBLEM:

Old bitumen based surface had blistered and broken down over time, resulting in water leaks through the ceiling to the plant room below. This condition has been accelerated by tradesmen leaving their mark on the surface as additional technology services have been installed.

SOLUTION:

Waterproof the entire surface with a waterproofing membrane, embedded with fibreglass matting. Special care taken to cover the joints to parapet wall and services equipment.

PRODUCTS:

Microl 200 waterproofing membrane, Sikaflex PRO, fibreglass matting