



## Repair and Seal Garage Floor

### PROBLEM:

Residential garage in new housing estate suffered from excessive dust, undulation and poor visual appearance. The garage entrance formed the security to the front door, adding importance to the area. As the concrete condition was 'caulky' with levelling problems which didn't allow the garage doors to be closed, the problem needed to be fixed.

### SOLUTION:

The job required a full concrete grind of the floor, patch and repair damaged zones as the first step of preparation. The finishing treatment was multiple coats of water based , two part, coloured epoxy coating



### PRODUCTS:

Sika MonoTop 620, Dimacoat WB Epoxy coating