



Restoration of Balcony and cornice decoration

PROBLEM:

Balcony was suffering from rusting reo, exploding the concrete from the edge of the concrete slab. Damage to the cornices and front detracted from the appearance of the premises.



SOLUTION:

Chase out 'drummy' concrete around the exposed 'reo', treat metal with rust inhibitor and metal primer.. Build back the lintel and cornices to match the original profile, then paint to finished look.



PRODUCTS:

Metal Primers, Contec PLUG, Sika Mono Top 615HB, Sikafloor 620, F R Micraflex, Classic Paints - Acrylic